To do list CPS-NG

Build status: **1192 Beta**	21518 lines of code

Pierre Chassang at 06/04/2023 13:03

==Later*==

Menu:
- ☑ Screen resolutions and scaling.
- ☑ Check Options keys colors
- ☑ Check Modules navigation process.
- ☑ Check navigation logic.
- ☑ Fix access violation at program shutdown*(after perf then back to Fuel then Perf then menu then exit program*)

Trip planner:
- ☑ Screen resolutions and scaling.
- ☑ Check Sub Steps Checkbox Click when reloading the module.
- ==Add Subsonic Minimum Distance, develop calculation function.*==
- ==Add Labels on flight map.*==
- ☑ DBPP to be finalized.
- ☑ ABPP to review according to DBPP.
- ☑ Check subsonic flight.
- ☑ Fix message 59%CG when subsonic flight.
- ☑ Check linear holding.
- ☑ Check Isolated airport procedure.
- ☑ Add GetSubsonicDistance dans edIcaoCodeKeyUp/TripPlanner
- ==Add FOB, EAT, and wind in the log.*==
- ☐ Check Active Sky.
- ☑ Check custom WX.
- ☑ Check unexcepted appearance of pln selector.
- ☑ Check Modules navigation process.
- ==Complete Distance2FL100 procedure/function==*
- ☑ Check CircIn and Out with new Subsonic step logic.
- ☑ Check navigation logic.

Load:
- ☑ Screen resolutions and scaling.
- ☐ Check image loading Process.
- ☑ Check Modules navigation process.
- ☑ Check navigation logic
- ☐ Check CG moving when click on Crew number.

Fuel:
- ☐ Finalize the appearance of messages.
- ☑ Screen resolutions and scaling.
- ☐ Check image loading Process.
- ☑ Check Modules navigation process.
- ☑ Fix Departure correction negative!
- ☑ Set Bloc CG when back from Performance.
- ☑ Check navigation logic
- ☑ Check Departure correction time
- ☑ Check Trip time
- ☐ Check T9/T11 transfer

Performance:
- ☑ Screen resolutions and scaling.
- ☐ Check EO Sid.
- ☐ Check image loading Process.

- ☑ Check Modules navigation process.
- ☑ Check navigation logic.

Control Panel:
- ☐ Check X-Plane paths options.
- ☐ Check FSX/P3D/MSFS paths options.
- ☐ Check Active Sky options.

Global Variables:
- ☐ Check all variables
- ☐ Delete all unused global variables.

Report:
- ☐ Check data under QNH and temperature.
- ☐ Check EO Sid.

Fuel slide rule:
- ☐ Drawing. In progress
- ☐ Development.
- ☐ Tests.

Manual:
- ☐ Modify in accordance with new or modified features.

Installation:
- ☐ Update.

Miscellaneous:
Change Metar source for OGIMET (provides historical weather)*